
Historic, Archive Document


Do not assume content reflects current scientific knowledge, policies, or practices.






REASONS WHY YOU SHOULD BE CAREFUL

351946 *REASON No. 1*




Loss of Property.

REASON No. 2



Loss of Life.

REASON No. 3



Loss of Food.

REASON No. 4



Loss of Job.

HOW TO BE CAREFUL

Look over the elevators and conveyors often, report at once any rubbing, slipping, friction, or other trouble, no matter how slight.

Also observe carefully these

four important DON'TS:

Never smoke in or near the mill or elevator.

Never strike a match anywhere on the premises.

Never use open flames, torches, candles, lanterns, or unprotected light bulbs in dusty air or when examining bins or elevator legs.

Never let dust accumulate on beams, machines, pulleys, or floors.

UNITED STATES GRAIN CORPORATION

Cooperating with the
United States Department of Agriculture
Bureau of Chemistry

